


1 Sand dunes eroded by public footfall with all front edge plant species eliminated. Rear marram dunes beginning to collapse into tide.



2 Protected front edge with fence. Plugs of sand couch planted at the front edge and lyme plugs behind up to marram area. Front edge of sand dunes advance two metres towards the sea.



3 Following re-establishment of front edge, the height of the sand dunes increases by 1.5m within ten months. The level of the sand on entire beach rises by nearly one metre and high tide retreats 15 metres.

